



Nothing else measures up!

Prospect House
George Cayley Drive
Clifton Moor
York
England
YO30 4XE

Tel: +44 (0) 1904 692723
Fax: +44 (0) 1904 690385

E-Mail: sales@yorksurvey.co.uk



S-Digit Mini+ Inclinometer



Code: 263040

Operating Instructions

S-Digit Mini+ Inclinometer

SUPPLIED WITH

- Electronic inclinometer S-Digit Mini+
- Padded bag
- Batteries
- User Manual

FUNCTIONS

Electronic slope measurer for measuring inclinations, slopes and plane surfaces.

Technical Data

Working range: 4 x 90°

Resolution: 0.1°/0.1%

Accuracy: 0° + 90° = ±0.1°; 1° - 89° = ±0.2°

Power supply: 3x AAA alkaline batteries


Operating time: 600hrs

Size: 156 x 56 x 31mm

Weight: 0.3kg incl batteries

POWER SUPPLY


Replace the batteries: Open the battery compartment cover and insert the batteries (ensure correct polarity). When replacing the batteries always power off the instrument.



When the batteries have been replaced, the instrument will power on automatically.



Display indication: "GOOD", then "-0-".




Now a calibration must be made - see "Check and Calibration".

Important: If the battery symbol flashes, the batteries need to be replaced.



FEATURES



1) Power

Power the instrument ON/OFF.

2) Hold/Illumination

Press the button short to freeze the current reading. Press the button long to switch on/off the illumination.


3) Mode

Press the button short to select 5 different display modes (see "Additional Functions").

4) Cal/Sound

Press the button short to switch on/off the signal tone.

Press the button long to switch on the calibration mode (see "Check of Calibration")



5) Direction symbol (approaching the 0°/90° position)

6) Symbol sound on/off

7) Battery status indicator

8) Unit symbol N/FT

9) Unit symbol °/°

10) Unit symbol mm/m

IMPORTANT

Calibration of inclinometer

- before first use

- before important measurements

- after a hit or drop


- after a large fluctuation in temperature

CHECK OF CALIBRATION

Set the instrument down on a flat and even surface and switch it on. Wait 3 seconds and note down the measured value (A). Turn the unit by 180° and set it down on the same position as before. Wait 3 seconds and note down the measured value (B). If the deviation between the two values, A and B, is more than 0.2° the unit has to be calibrated.

CALIBRATION

Set the instrument down on the same flat and even surface, switch it on and keep the button CAL/SOUND pressed until the display shows "-0-". Wait approximately 3 seconds and press the button CAL/SOUND again until the display shows "-1-". Turn the unit by 180° and set it down on the same position as before. Wait approximately 3 seconds and press the button CAL/SOUND again until the display shows "-2-". Now the calibration is completed.



MEASUREMENT OF INCLINATION

The two arrows in the display indicate in which direction the instrument has to be moved in order to reach the 0° or 90° position.



The exact 0° or 90° position is shown by double arrows.



The display has an automatic digit inversion for overhead measurements.



ADDITIONAL FUNCTIONS

Automatic shut-off

If no button is used for 20min the instrument will power off automatically.

Sound

Switch the sound function on. The instrument will now show by a sound signal if the horizontal or vertical position approaches. The closer the position is, the denser the sound signal will be. If the instrument is in correct vertical or horizontal position, the sound will be continuous.

Mode functions[(1) - (5)]

1) Slope indication in ° (14.5°)

2) Slope indication in % (25.9%)

3) Indication IN/FT (3 1/8 IN/FT)

4) Indication IN/FT (3.10 IN/FT)

5) Indication mm/m (258.9mm/m)

Keep the mode button pressed to have all mode functions switch fast. The display will not show any values. Release the mode button to return to the standard indication.

CONNECTION TO CAMERA TRIPOD

With 1/4" thread (at the bottom side) S-Digit Mini+ can be connected to a camera tripod.

SPECIAL FEATURE WITHIN THE RANGE OF 0° - 90°

0-setting in any position required:

In the range between 0° and 90° the ZERO layer can be defined in any position.

Start the calibration function in the position required (press CAL/SOUND longer than 3 seconds) - wait 3 seconds - press CAL/SOUND again - wait 3 seconds - press CAL/SOUND again - finalised.

Do not turn the S-Digit Mini+ during this process.

Now the ZERO layer is defined in the new position and the application required can be started.

ATTENTION:

We recommend to define the ZERO layer in the horizontal position again when you have finished your application. Otherwise it may happen that for the following measurements the results can be completely wrong (e.g. when you work the next day or if another user is working with the unit).

SAFETY NOTES

CARE AND CLEANING

Handle measuring instruments with care. Clean with soft cloth only after any use. If necessary, damp the cloth with some water. If the instrument is wet, clean and dry it carefully. Pack it up only if it is perfectly dry. Transport in original container/case only.

SAFETY INSTRUCTIONS

- Follow the instructions given in the user manual.
- Use the instrument for measuring jobs only.
- Do not open the instrument housing. Repairs should be carried out by authorised workshops only.
- Please contact York Survey Supply Centre.
- Do not remove warning labels or safety instructions.
- Keep the instrument away from children.
- Do not use the instrument in explosive environments.

- The user manual must always be kept with the instrument.

SPECIFIC REASONS FOR ERRONEOUS MEASURING RESULTS

Measurements through glass or plastic windows; dirty laser emitting windows; after the instrument has been dropped or hit, please check the accuracy.

Large fluctuation of temperature: If the instrument will be used in cold areas after being stored in warm areas (and vice versa) please wait some minutes before carrying out measurements.

ELECTROMAGNETIC ACCEPTABILITY (EMC)

It cannot be completely excluded that this instrument will disturb other instruments (e.g. navigation systems); will be disturbed by other instruments (e.g. intensive electromagnetic radiation, nearby industrial facilities or radio transmitters).

CE CONFORMITY

Instrument has the CE-mark according to EN 61326:1997, EN 55022, EN 61000-4-2/-3.

WARRANTY

- The product is warranted by the manufacturer to the original purchaser to be free from defects in material and workmanship under normal use for a period of two (2) years from the date of purchase.
- During the warranty period, and upon proof of purchase, the product will be repaired or replaced (with the same or similar model at manufacturer's option), without charge for either parts or labour.
- In case of a defect please contact the dealer where you originally purchased this product. The warranty will not apply to this product if it has been misused, abused or altered. Without limiting the foregoing, leakage of the battery, bending or dropping the unit are presumed to be defects resulting from misuse or abuse.

EXCEPTIONS FROM RESPONSIBILITY

- The user of this product is expected to follow the instructions given in operator's manual. Although all instruments left our warehouse in perfect condition and adjustment the user is expected to carry out periodic checks of the products accuracy and general performance.
- The manufacturer or its representatives assumes no responsibility of results of a faulty or intentional usage or misuse including any direct, indirect, consequential damage and loss of profits.
- The manufacturer or its representatives assumes no responsibility for consequential damage and loss of profits by any disaster (earthquake, storm, flood, etc.), fire, accident or an act of a third party and/or a usage in other than usual conditions.
- The manufacturer or its representatives assumes no responsibility for any damage and loss of profits due to a change of data, loss of data and interruption of business etc. caused by using the product or an unusable product.
- The manufacturer or its representatives assumes no responsibility for any damage and loss of profits caused by usage other than explained in the user's manual.
- The manufacturer or its representatives assumes no responsibility for damage caused by wrong movement or action due to connecting with other products.